Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

693 POLE 66490 NY Spills S105141994
NNE VILLAGE CT/VILLAGE RD SO N/A

NNE VILLAGE CT/VILLAGE RD SO 1/2-1 BROOKLYN, NY

0.997 mi. 5262 ft.

Relative: SPILLS: Higher Name: POLE 66490

Actual: Address: VILLAGE CT/VILLAGE RD SO

15 ft. City,State,Zip: BROOKLYN, NY Spill Number/Closed Date: 0105931 / 2001-11-23

 Facility ID:
 0105931

 Facility Type:
 ER

 DER Facility ID:
 74840

 Site ID:
 80807

 DEC Region:
 2

Spill Cause: Equipment Failure

 Spill Class:
 C4

 SWIS:
 2401

 Spill Date:
 2001-09-04

 Investigator:
 JHOCONNE

 Referred To:
 Not reported

 Reported to Dept:
 2001-09-04

 CID:
 270

Water Affected: Not reported

Spill Source: Institutional, Educational, Gov., Other

Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 2001-09-04
Spill Record Last Update: 2001-11-23
Spiller Name: CALLER
Spiller Company: CON ED

Spiller Address: 128 WEST END AVE

Spiller Company: 001 Contact Name: CALLER

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was

O'CONNELL e2mis notes: Approx. 30 gallons non-PCB dielectric fluid (from pole-mount transformer) on concrete, asphalt amd in sewer. Absorbent was placed and sewer protected. There ewas fire involved.Sample to be taken from spill. At 0930 unit was taken off line, plugged and bagged. FDNY on location. Astoria tanker dispatched. 9/4/01, 1534 hrs: lab resutls <1 ppm PCB 9/4/01, 1700 hrs: clean up complete.(JHO) DEC responder notes (Foley): Transformer is on Village Ct. Con Ed power washing Willage Rd. South. Con Ed and Clean Harbors will work together to finish job. Sewer to be cleaned out. Transformer is bagged. Village Rd. South was completely cleaned by Con Ed crew. Village Ct to be triple washed. Estimated 30-40 gal capacity on transformer - most went to sewer. Approx 5 gal on street."

Not reported

Remarks: "in sewer also, clean up crew on the way, pcb unknown "

All Materials:

Site ID: 80807
Operable Unit ID: 842966
Operable Unit: 01

Map ID
Direction
Distance
Elevation Site

MAP FINDINGS

EDR ID Number
Database(s) EPA ID Number

Material ID: 530819 Material Code: 0020A Material Name: transformer oil Not reported Case No.: Material FA: Petroleum Quantity: 5.00 Units: G Recovered: .00

Oxygenate: Not reported